Regd. Trade Mark


for No. Oa OUTFIT

Binns Road, Liverpool 13

INSTRUCTIONS

Copyright by Meccano Ltd

No. 61.Oa



MODEL-BUILDING WITH MECCANO

SOME USEFUL HINTS

It will be noticed that with each model in this Book of Instructions is given a list of the parts required to build it. For the first few models it is a good plan to lay out on the table all the parts required for the one it is proposed to build, and put the remainder of the Outfit to one side. To help you pick out the correct parts for your model a complete list of Meccano parts is given at the back of this Book, and all the principal parts are illustrated. In the list the parts are all numbered, and in most cases, their measurements are given. There is no need, however, to measure the parts to find out which is which, as the size is easily found from the number of holes. All Meccano holes are spaced $\frac{1}{2}$ " apart, so that by counting two holes to the inch the size of a part can be found at once. For instance, Part No. 2 is listed as a $5\frac{1}{2}$ " Perforated Strip, so you look in your Outfit for a Strip with eleven holes. Similarly, No. 189 is a $5\frac{1}{2}$ " Flexible Plate, so you look for a Flexible Plate eleven holes in length and three holes in width.

Beginners sometimes wonder which section of a model should be built first. There cannot be any definite rule for this, as it depends on the design of the model. In stationary models the base usually should be built first. In most of the small models a $5\frac{1}{2}''\times2\frac{1}{2}''$ Flanged Plate forms an important part of the structure, and often the best plan is to start building by bolting parts to this Plate. For other models a good general rule is that the sections that form supports for a number of other parts should be built first.

THE IMPORTANCE OF LOCK-NUTTING

In some models it is necessary to join certain parts together so that, although they cannot come apart, they are free to pivot or move in relation to one another. To do this the parts are bolted together as usual but the nut is not screwed up tightly, so that the parts are not gripped. Then, to prevent the nut from unscrewing, a second nut is screwed up tightly against it, the first nut being held with a spanner. This method of using a second nut is known as *Lock-nutting*.

A Rod is usually mounted in a support or bearing, such as a hole in a strip, so that it is free to revolve. The Rod is then said to be *Journalled* in the Strip.

DRIVING YOUR MODELS

Models can be driven by means of either clockwork or electric motors. Ask your dealer for details of these Meccano Motors. Small and light models can be driven direct from the driving pulley of the motor or through a belt running over two pulleys of the

same size giving what is known as a 1:1 (one-to-one) ratio. A better plan, however, is to take the drive from a small pulley on the motor shaft to a larger pulley on the driving shaft of the model. In most cases a 1" Pulley on the motor shaft and a 3" Pulley on the model shaft will be found satisfactory. This provides a reduction ratio of approximately 3:1.

Rubber bands are very convenient for driving belts. Sometimes, however, a rubber band of the right length is not available, and then Meccano Cord or thin string is used. To tie the Cord to form an endless belt you should use the familiar reef knot.

With the larger Outfits, belt drive can be replaced with advantage by gearing. To operate a slow-moving model demanding great power, such as a traction engine, gears that will provide a considerable reduction must be used. For example, a Worm meshed with a ½" Pinion will give a 19:1 reduction; a Worm meshed with a 57-tooth Gear will give a 57:1 reduction.


If the Motor is to operate successfully, however, you must make sure that there is no excessive friction in the mechanism of the model. This can be caused by shaft bearings being slightly out of line, or by a belt or Cord drive being too tight. Before condemning your motor, therefore, first make sure that every revolving shaft moves quite freely in its bearings, and that the bearings are in line with one another. The bearings can be brought into line by pushing through them a Drift (Part No. 36c) or a Rod, before the bolts holding the various parts are tightened up. Then apply a little light machine oil to every bearing or pivot on which moving parts are mounted.

Triangular Flexible Plates and Flexible Plates can be used for forming curved surfaces in models, but they should not be bent at a too sharp angle. With careful handling these Plates can be bent to the required curve and after use straightened again.

All Outfits from No. 2 upward include the Cord Anchoring Spring, Part No. 176. This part provides a neat and positive method of fastening a length of Cord to a Rod. The Spring is pushed on to a Rod or Crank Handle by turning it in such a way that its coils tend to unwind.


MECCANO SERVICE


If ever you are in any difficulty with your models, or if you want advice on anything connected with this great hobby, write to us. We shall be delighted to help you in any way possible. Addresss your letters to *Information Service*, Meccano Ltd, Binns Road, Liverpool 13.



I.4 RAILWAY BREAKDOWN CRANE

The hoisting Cord is secured to the Crank Handle and then led over the \S^m Bolt (1). It is then passed through the pulley block and fastened to the jib at (2). The jib is attached to the Bush Wheel (3) by means of Angle Brackets, and the complete unit is pivoted as follows. A \S^m Bolt is passed through the $5\S^m \times 2\S^m$ Flanged Plate from the underside, and is secured in the boss of the Bush Wheel by its set screw.






1.5 TRICYCLE VAN


Parts Required

4	of	No.	2	1 1	of	No.	17	1 24	of	No.	37b	2	of	No.	111c
3	22	,,	5	3	27	"	22	3	99	"	38	2	"	, ,,	126
3	22	"	10	1	"	33	24	2	"	**	48a	2	"	22	126a
6	**	22	12	4	27	33	35	1	"	"	52	2	- 33	22	142c
2	22	22	16	27	"	37	37a	2	"	22	90a	2	,,	22	189



The frame of the cycle consists of two 5½" Strips (1) connected at one end by a bolt that fixes them also to an Angle Bracket (2). The Angle Bracket pivots on a bolt *lock-nutted* to the Flanged Plate. The seat is carried by three 2½" Strips (3), each of which is connected by an Angle Bracket to the Flat Trunnion (4). The front axle is carried in Trunnions bolted underneath the Flanged Plate.

1.3 RACING SEAPLANE




Parts Required

3	of	No.	2	1	of	No.	24	2	of	No.	111c
3	22	,,	5	20	,,	21	37a	2	"	"	126
4	22	"	10	19	"	**	37b	1	"	,,	126a
8	"	"	12	1	,,	,,	48a	2	**	,,	189


1.6 STAMPING MILL

The anvil (1) is made up of two Trunnions bolted together, When the Crank Handle is rotated, the Fishplates bolted to the Bush Wheel strike the centre 1" Pulley on the hammer shaft and cause it to rise and fall.

Parts Required No. 2 | 1 of No. 90a



1.7 MOTOR LORRY



guards are each fastened to the sides nut, with a Spring Clip between the the 5½" Strip to form a distance piece.	mudgu	
AND THE RESIDENCE OF THE PROPERTY OF THE PROPE	Dante	Paguiro


10

							Parts	Requ	ure	D					
4	of	No.	2	1 4	of	No.	22	1 2	of	No.	48a	2	of	No.	126
		22	5	1	22	22	24	1	22	33	52	2	35	25	126a
3	39	"	12	2	,,	22	35	2	32	22	90a	4	**	22	155
2	"	"	16	23	"	"	37a	3	,,	22	111c	2	"	37	189
1	,,	"	17								125				

1.8 MECHANICAL SHOVEL

The Bolts (1), on which the jib pivots, are *lock-nutted*. The shovel arm is pivoted on a 2" Rod and the shovel is supported by a Cord that passes over the $\frac{1}{8}$ " Bolt at the jib head and is fastened to a $2\frac{1}{8}$ " $\times \frac{1}{8}$ " Double Angle Strip as shown. The Cord (2) is fastened to the jib and then passes over a $3\frac{1}{8}$ " Rod journalled in the holes above the $2\frac{1}{8}$ " Curved Strips, and is attached to a Fishplate fastened by the *lock-nutted* Bolt (3) to the Bush Wheel.

to a Fishplate fastened by the *lock-nutted* Bolt (3) to the Bush Wheel. When the Crank Handle is rotated, the Bush Wheel imparts a digging motion to the jib




37b

155


1.9 WINDMILL

The sails are gripped on the $3\frac{1}{2}$ " Rod by the 1" Pulley (with Rubber Ring) at the front and another 1" Pulley at the back of the sails. The Pulleys are pressed against the faces of the sails and locked on the Rod.



Parts	Required	۰

				Fal	LS	Requ	nred					
4	of	No.	2	1 1	of	No.	24 1	1	of	No.	52	
4	11	33	5	3	22	22	35	2	22		90a	
1	22	32	10	24	22	. 22	37a	2	,,,	"	126	
4	33	52	12	24	22	12	37b	2	,,	"	126a	
1	"	**	16	4	"	>>	38	1	22	"	155	
1	"	22	195	1	"	**	40	2	**	22	189	
4	"	22	22	2	22	93	48a					




3	of	No.	2	1 4	of	No.	22	1	of	No.	40	2	of	No.	126
		**	5	1	22	22	24	2	. 33	**	48a	2	,,	22	126a
2	,,	22	10	1	22	22	35	1	22	,,	52	4	,,	22	155
5	"	22	12	24	,,	"	37a	2	"	,,	90a	1	22	"	139
2	"	22	16	20	**	"	37b	2	"	. "	111c				
1	,,	22	17	4	**	**	38	1	**	55	125				1

Parts Required

2 " " 189

I.II STEAM WAGON

The front axle is supported in a $2\frac{1}{2}'' \times \frac{1}{2}''$ Double Angle Strip (1) lock-nutted to a $\frac{1}{2}''$ Reversed Angle Bracket (2). The Reversed Angle Bracket is bolted to a $5\frac{1}{2}''$ Strip fixed to the centre of the Flanged Plate. The boiler is a $5\frac{1}{2}'' \times 1\frac{1}{2}''$ Flexible Plate rolled into a cylinder, and the Bush Wheel (3) is attached to an Angle Bracket. The roof is made from two Flat Trunnions bolted to a $2\frac{1}{2}'' \times \frac{1}{2}''$ Double Angle Strip (4). The Curved Strips (5) are connected to the Flat Trunnions by Fishplates. A Trunnion (6) at each side is spaced from the Flanged Plate by two Washers.




Note: The Loaded Sacks (Part No. 122) are not included in the Outfit

1.12 FLYING BOATS Parts Required 4 of No. 12 16 195 22 24 35 37a 37b 38 40 48a 52 90a 125 126 126a 189


1.13 CIRCULAR SAW

The Bush Wheel (1) is fixed to a $3\frac{1}{2}$ " Rod that is passed through two Trunnions bolted to the Flanged Plate.




1.14 GYMNAST

The Bolts (1) are *lock-nutted*. The bearings for the Crank Handle in the Flexible Plates are reinforced by Trunnions bolted to the Flanged Plate.




Parts Required


				0.00	4.0						
4	of	No.	2	1 1	of	No.	24	1	of	No.	52
4	22	"	5	2	32	22	35	2	**	55	90a
1	**	**	10	29	33	,,,	37a	4	22	"	111c
4	"	**	12	24	**	17	37b	2	,,	**	126
1	,,	"	16	4	12	,,	38 40	2	,,	27	126a
1	12	,,	19s	1	27	22	40	2	"	22	189
4	. 33	"	22	2	"	23	48a				



1.16 DRILLING MACHINE



1.17 COSTER AND BARROW




Parts Required 27 of No. 37a 24 " " 37b


3 " " 5 | 24 " " 37b 4 " " 10 | 4 " " 38 6 " " 12 | 2 " " 48a 1 " " 16 | 1 " " 52 1 " " 17 | 2 " " 90a 4 " " 22 | 3 " " 111c 2 " " 142c 1 " " 155 1 *Magic* Clock-

2 of No. 126a


1 Magic Clockwork Motor (not included in Outfit)



1.18 LIFTING BRIDGE



1.19 MECHANICAL SWING




The left-hand $2\frac{1}{5}$ " Strip that supports the swing is connected to the Crank Handle by passing the set screw of the 1" Pulley (2) through a hole in an Angle Bracket bolted to the Strip and then into the boss of the Pulley, Bolt (1) on the Bush Wheel is fitted with *lock-nuts*.


1.20 DERRICK CRANE

The jib is bolted to a Bush Wheel (1), which is fixed by its set-screw on a 1" Bolt passed through the Flanged Plate. The jib supporting Cord is passed round a 1" Pulley on a 2" Rod (2). This Rod is held in place by a Spring Clip placed underneath the Flat Trunnion.

The brake lever is lock-nutted to a 1" Reversed Angle Bracket (3). A brake is provided by a length of Cord passed over Pulley (4) and tied to the lever and to the Flanged Plate.



1.21 OPEN TRAMCAR



Parts Required

2	of	No.	5	1 -	10	of	No.	19s	1	1	of	No.	52
4	22	22	10		1	17	23	22	- h	2	22	22	90a
7	" "	23	12		1	22	**	24	= .	4	99	22	111c
2	22	22	16		1	57	"	35		1	35	37	125
				2	7	,,	22	37a		2	22	**	126
				2.	1	"	22	37b		2	55	**	126a
						55	22	40		4	53	33	155
)	,,	22	48a		2	"	23	189
0	1												
P		0	1										
			0	9 0									
-				30	1	1							
-				1				1	-	_ 3			

1.22 FIRE ENGINE

Bolts (1) at each side are lock-nutted. The sides of the ladder are held together by two Angle Brackets (2), which are bolted together to form a 'U'-shaped bracket. The rear axle bearings (3) are Fishplates bolted inside the flange of the Flanged Plate. The Cord from the Crank Handle is tied in the fourth hole up the ladder so that when the Handle is turned it causes the ladder to lift. Parts Required 4 of No. 37b 126a 155


1.23 MOBILE CRANE

				Par	ts	Requ	ired					
4	of	No.	2	4	of	No.	35	1	3	of	No.	111c
4	"	,,	5	29	**	11	37a		1	**	,,	125
1	11	**	10	23	55	**	37b		2	99	,,	126
4	,,	,,	12	2	,,	"	38		2	33	"	126a
2	11	,,,	16	1	27	,,	40	-	2	"	,,	142c
2	"	22	17	2	27	,,	48a		2	,,	22	155 -
1	77	22	19s	1	"	22	52		2	22	,,,	189
4	11	**	22	1	35	,,	57c					
1	,,	**	24	2	22	22	90a					

For more new models to build, see the

MECCANO MAGAZINE

which is published on the first of every month.



1.24 POWER PRESS

The Bolts (1) are lock-nutted and the Angle Bracket at the lower end of the 2½" Strip has a 3½" Rod in its elongated Rod in its elongated hole, where it is held by means of two Spring Clips. The Rod forming the press ram moves up and down in the

circular holes of a Fishplate bolted to a 2½ ×½" Double Angle Strip and also through the centre hole of another 2½" ×½" Double Angle Strip.

Fig. 1.24






Fig. 1.24a

155

189




1.25 TRIP HAMMER



Pai	rts	Req	uired
4	of	No.	2
3	**	**	5
2	**	**	12
1	**	"	17
1	**	"	195
4	,,	**	22
1	**	"	24
4	12	"	35
17	"	"	37a
17	22	,,	37b
1	**	"	48a
1	22	22	52
2	**	"	1110
1	,,	**	125
2	"	**	126
2	12	,,	126a
1	"	"	155
1	,,	27	189

1.26 SIDE TIPPING WAGON

				Par	ts	Req	uired				
3	of	No.	2	28	of	No.	37a	1	of	No.	125
4	,,	,,	5	24	,,	,,	37b	2	27	"	126
4	22	33	10	3	.,,	55	38	2	.99	22	126a
7	,,	"	12	1	,,	"	40	4	"	22	155
2	"	"	16	2	22	22	48a	2	11	**	189
1	,,	,,	17	1	,,	"	52	-			
4	,,	**	22	2	,,	22	90a	1	Mo	gic 1	1otor
1	"	"	24	4	**	,,	111c	(no	t ind	luded	Outfit)




Each of the Bolts (1) is *lock-nutted*. A piece of Cord is fastened to the Rod (2) (Fig. 1.26a) wrapped round it two or three times, and then is taken through the hole in the Flanged Plate above the Rod and secured to the Angle Bracket (3). By turning the Bush Wheel the container is tipped sideways.

1.27 TRAVELLING CRANE

Parts Required

4	of	No.	2	1 1	of	No.	17	1 20	of	No.	37a	1 1	of	No.	52
4	33	22	5	1	"	22	19s	20	"	27	37b	1	,,	99	57c
4	,,	22	10	4	,,	22	22	4	22	22	38	2	**	55	90a
2	22	22	12	1	,,	22	24	1	"	22	40	- 1	- 22	**	111c
2	22	22	16	4	**	59	35	1	,,	"	48a	2	,,	**	126
												2	- 22	**	126a




The sides of the jib are secured to the Bush Wheel (1) by two Angle Brackets (2), one on each side. A $\frac{3}{8}$ " Bolt is passed from the underneath side of Double Angle Strip (3) into the boss of the Bush Wheel (1) and the serve wis then tightened.


Wheel (1) and the set screw is then tightened. The Flat Trunnions it he lower end of the jib support the Crank Handle, which also passes through Fishplates bolted to the Angle Brackets (2) on the Bush Wheel (1). The Cord is fastened to the Crank Handle, and passes over the 2" Rod at the jib head.


1.28 ANTI-AIRCRAFT GUN


Fig. 1.26a



















HOW TO CONTINUE

When you have built all the models shown in this Book of Instructions, you will be keen to build others bigger of Instructions, you will be keen to build others bigger and more elaborate. Your next step is to purchase a Meccano No. Ia Accessory Outfit containing all the parts required to convert your No. I into a No. 2 Outfit. You will then be able to build the full range of No. 2 Outfit models, a few of which are illustrated on this page. If you prefer to do so, you can build up and develop your Outfit quite easily by adding various parts to it from time to time. The variety of models you can make with Meccano is almost unlimited, and the more Meccano parts you have the bigger and better your models will be.

BUILD BIGGER AND BETTER MODELS









Tractor

Here is a selection of five models that are illustrated and described in the Instructions Book packed with Meccano Outfit No. 2.



Punching Machine

MECCANO PARTS





204

PULLEYS 19b. 3" diam., with boss and screw 19c. 6" diam., with boss and screw 20a. 2" diam., with boss and screw 21. 1½" diam., with boss and screw 22. 1" diam., with boss and screw





PULLEYS

22a. 1" diam., without boss 23. ½" diam., without boss 23a. ½" diam., with boss and screw









24. Bush Wheel, 13" diam., eight holes 24a. Wheel Disc, 13" diam., without boss, eight holes 24b. Bush Wheel, 13" diam., six holes 24c. Wheel Disc, 13" diam., without boss, six holes

PINIONS

diam., $\frac{1}{4}$ " face, 25 teeth diam., $\frac{1}{2}$ " face, 25 teeth 25a. face, 25 teeth diam 26. face, 19 teeth diam., diam., 1" face, 19 teeth 25a. 25b. ' diam., ﷺ face, 19 teeth ' diam., ‡" face, 15 teeth







GEAR WHEELS

27. $1\frac{1}{4}''$ diam., 50 teeth 27a. $1\frac{1}{4}''$ diam., 57 teeth 27b. $3\frac{1}{2}''$ diam., 133 teeth 27c. $2\frac{1}{4}''$ diam., 95 teeth 27d. $1\frac{1}{8}''$ diam., 60 teeth





CONTRATE WHEELS

1½" diam., 50 teeth









Bevel Gear, $\frac{7}{8}$ " diam., 26 teeth (for use in pairs) Bevel Gear, $\frac{4}{3}$ " diam., 16 teeth Can only be Bevel Gear, $\frac{1}{3}$ " diam., 48 teeth Cuset together Gear Wheel, 1" diam., $\frac{4}{3}$ " face, 38 teeth Worm, ½" diam.

Spanner







Box Spanner Spring Clip

Screwdriver Screwdriver (longer)

36c. 37. 37a. Drift (for levering bolt holes into line) Nut and Bolt, 32"

Nut 37b. Bolt, 7/2" Washer Washer, 3"

38. 38d.

Hank of Cord



41. Propeller Blade 43. Tension Spring, 2" long







44. Bent Strip, stepped Double Bent Strip

DOUBLE ANGLE STRIPS

47. 47a. 48a. 48b.



Slide Piece 50. Slide Piece 51. Flanged Plate, $2\frac{1}{2}" \times 1\frac{1}{2}"$ 52. Flanged Plate, $5\frac{1}{2}" \times 2\frac{1}{2}"$ 52a. Flat Plate, $5\frac{1}{2}" \times 3\frac{1}{2}"$ 53. Flanged Plate, $3\frac{1}{2}" \times 2\frac{1}{2}"$ 53a. Flat Plate, $4\frac{1}{2}" \times 2\frac{1}{2}"$





Flanged Sector Plate, 4½" long Perforated Strip, slotted, 5½" long Perforated Strip, slotted, 2" long





57b. Hook, Loaded, Large 57c. Hook, Loaded, Small 58. Spring Cord, 40" length 5/b. Hook, Loaded, Large 57c. Hook, Loaded, Small 58. Spring Cord, 40" length 58a. Coupling Screw for Spi 58b. Hook for Spring Cord 59. Collar, with screw Coupling Screw for Spring Cord







Windmill Sail Crank

62a. Threaded Crank 62b. Double Arm Crank







63. Coupling 63b. Strip Coupling 63c. Threaded Coupling 63d. Short Coupling





Threaded Boss Centre Fork Set Screw, &

69a. Grub Screw, 15" 69b. Grub Screw, 15" 69c. Grub Screw, 64



78. 79. 79a.





Flat Plate, $5\frac{1}{2}$ " \times $2\frac{1}{2}$ " Flat Plate, $2\frac{1}{2}$ " \times $2\frac{1}{2}$ " Flat Plate, 3" \times $1\frac{1}{2}$ " 70. 72. 73.

Triangular Plate, 2½"
Triangular Plate, 1"





SCREWED RODS

80a. 3½° 80b. 4½°

81. 82.

CURVED STRIPS

89. 5½" (10" radius) 89a. Stepped, 3" (1¾" radius) 89b. Stepped, 4" (4½" radius) 90. 2½" (2¾" radius) 90a. Stepped, 2½" (1¾" radius)





94. Sprocket Chain, 40" length

SPROCKET WHEELS

2" diam., 36 teeth 96. 1" diam., 18 teeth 95a 1½" diam., 28 teeth 95b 3" diam. 56 teeth 96a. 3" diam., 14 teeth diam., 56 teeth



99

BRACED GIRDERS

97. 97a. 12½" long 9½" long 7½" long 100. 5½" long 100a. 4½" long long 99a. 2½" long 99Ь.





101. Heald for Loom 1 102. Single Bent Strip




FLAT GIRDERS

103. 5½" long 103a. 9½" long 103b. 12½" long 103c. 4½" long 103d. 3½" long 103e. 3" long 103f. 2½" long 103g. 2" long

103h. 1½" long 103k. 7½" long

MECCANO PARTS



Wood Roller (complete with Rod and two Collars)

Corner Gusset

Face Plate, 21" diam.





110. Rack Strip, 34" long 1 110a. Rack Strip, 64" long

BOLTS

111. ½" 111a. ½"

113. Girder Frame







Threaded Pin

116. Fork Piece, large 116a. Fork Piece, small



118. Hub Disc, 51" diam.





120b. Compression Spring, %" long 122. Loaded Sack





Cone Pulley, 1¼", 1" and ¾" diam. Reversed Angle Bracket, 1" Reversed Angle Bracket, ½"







126. Trunnion 126a. Flat Trunnion 128. Bell Crank, with Boss





Eccentric, Triple Throw, \(\frac{1}{4}\)", \(\frac{3}{8}\)" and Eccentric, Single Throw, \(\frac{1}{4}\)" 130. 130a





Corner Bracket, 1½" Corner Bracket, 1" Crank Shaft, 1" stroke





Handrail Support | 136a, Handrail Coupling





137. Wheel Flange

1 138. Ship's Funnel, Raked





Flanged Bracket (right) 139a. Flanged Bracket (left) Universal Coupling







142a. Motor Tyre (to fit 2" diam. rim) 142b. Motor Tyre (to fit 3" diam. rim) 142c. Motor Tyre (to fit 1" diam. rim) 142d. Motor Tyre (to fit 1\frac{1}{2}" diam. rim) 142d. Motor Tyre (to fit 1\frac{1}{2}" diam. rim)

144. Dog Clutch





145. Circular Strip, 7½" diam. overall 146. Circular Plate, 6" diam. overall 146a. Circular Plate, 4" diam. overall







Pawl, with Pivot Bolt and Nuts

147a. Pawl Pivot Bolt, with two Nuts 147b.

Pawl, without boss 147c.

147c. Pawl, without boss
148. Ratchet Wheel
151. Single Pulley Block
153. Triple Pulley Block
154. Corner Angle Bracket, ½" (right-hand)
154b. Corner Angle Bracket, ½" (left-hand)
155. Rubber Ring (for 1" Pulley)







Fan, 2" diam. Channel Bearing, 1½"×1"×½"
Girder Bracket, 2"×1"×½"






162. Boiler, complete, 5" long × 2 1/6" diam.
 162a. Boiler Ends, 2 1/6" diam. × 3"
 163. Sleeve Piece, 1½" long × 1/6" diam.
 164. Chimney Adaptor, 3" diam. × ½" high







Swivel Bearing

165. Swivel Bearing
166. End Bearing
167b. Flanged Ring, 9¾ diam.
168. Ball Thrust Bearing, 4″ diam.
168a. Ball Thrust Race, flanged disc, 3¾″ diam.
168b. Ball Thrust Race, toothed disc, 4″ diam.
168c Ball Cage, 3¾″ diam., complete with balls
168d. Ball, ¾″ diam.





Socket Coupling Adaptor for Screwed Rod Flexible Coupling Unit Anchoring Spring for Cord





Rod Socket Gear Ring, 3½" diam. (133 ext. teeth, 95 int.)





Steering Wheel, 13" diam.

DRIVING BANDS

186c. 10" (heavy) 186d. 15" (heavy) 186e. 20" (heavy) 10" (light)

187. Road Wheel, 2½" diam. 187a. Conical Disc, 1½" diam.



FLEXIBLE PLATES

STRIP PLATES

197. 12½"×2½"







Hinged Flat Plate, $4\frac{1}{2}'' \times 2\frac{1}{2}''$ Curved Plate, 'U'-section, $2\frac{1}{2}'' \times 2\frac{1}{2}'' \times \frac{3}{2}''$ radius Curved Plate. $2\frac{1}{2}'' \times 2\frac{1}{2}'' \times 1\frac{1}{16}''$ radius 198. 199. 200.



2114 & 211B





211a. Helical Gear, ½" Can only be used 211b. Helical Gear, 1½" Can only be used 212. Rod and Strip Connector

212. Rod and Strip Connector, right-angle 213a. Rod Connector 213a. Three-way Rod Connector 213b. Three-way Rod Connector with boss



214. Semi-circular Plate, 21/2"





215. Formed Slotted Strip, 3" Cylinder, 2½" long, 1¼" diam.

TRIANGULAR FLEXIBLE PLATES

2½"×1½" 2½"×2" 224. 4" Rod with Keyway 223, $2\frac{1}{2}$ " $\times 2\frac{1}{2}$ " $\times 2\frac{1}{2}$ " $\times 1\frac{1}{2}$ " 226. 222.

230. 231. Key Bolt