

Price List

No. 0. Meccano Outfit 4/6

REVISED PRICES

No.	Description	s.	d.	No.	Description	s.	d.
No. 0	Meccano Outfit	5	0	No. 0A	Meccano Accessory Outfit	4	0
" 1	" "	8	6	" 1A	" "	8	0
" 2	" "	15	0	" 2A	" "	9	0
" 3	" "	22	6	" 3A	" "	16	6
" 4	" "	37	6	" 4A	" "	14	0
" 5	" " (Carton)	52	6	" 5A (Carton)	" "	45	0
" 5	" " (Wood)	75	0	" 5A (Wood)	" "	70	0
" 6	" "	130	0				
No. 1	Perforated Strips, 12½" long	-	-	-	½-dozen	1	3
" 2	" " 5½" "	-	-	-	"	0	9
" 3	" " 3½" "	-	-	-	"	1	9
" 8	Angle Girders 12½" "	-	-	-	"	1	0
" 9	" " 5½" "	-	-	-	"	0	6
" 52	Perforated Flanged Plates, 5½" x 2½"	-	-	-	each	0	5
" 53	" " " 3½" x 2½"	-	-	-	"	0	5
" 54	" " " sector	-	-	-	"	1	6
" 56	Manuals of Instructions	-	-	-	"	1	0
" 58	Spring Cord	-	-	-	per length	1	0
" 94	Sprocket Chain	-	-	-	per yard	1	0
" 99	Braced Girders, 12½" long-	-	-	-	½-dozen	1	9
" 105	Reed Hooks	-	-	-	each	0	3

Mar. 1st 1918.

NO. 5A. " " a No. 5 Outfit into a No. 6) ... 37/6

Do. " " Packed in superior oak cabinet with lock and key 60/-

Meccano Inventors' Accessory Outfit 7/6

Meccano Outfits with Electric Motors: No. 1x, 13/6; No. 2x, 19/6; No. 3x, 30/-

... .. 7/6
 13/6
 20/-
 32/6
 47/6
 in neat and well-made cardboard box
 67/6

 superior oak cabinet with lock and key
 ditto 115/-

sufficient parts to convert
 No. 0 Outfit into a No. 1) 3/6
 sufficient parts to convert
 it into a No. 2) ... 7/-
 sufficient parts to convert
 it into a No. 3) ... 8/-
 sufficient parts to convert
 it into a No. 4) ... 13/6
 sufficient parts to convert
 it into a No. 5) ... 14/-
 sufficient parts to convert
 it into a No. 6) ... 37/6