

SPECIAL NOTE TO LEAFLET No. 2

SHIP COALER

Since the publication of this leaflet the manufacture of the High Voltage Motor and the 4-volt Motor has been discontinued ; and these Motors have been replaced by a 6-volt Motor. No difficulty should be experienced in incorporating the 6-volt Motor in this model, as it is secured in place in a similar manner to that shown in Fig. 1. No alteration need be made to the gearing.