

AUSTRALIA,
NEW ZEALAND,
SOUTH AFRICA.

Meccano Price List

MAY, 1919.

No.		£	s.	d.
0.	Meccano Outfit	0	8	0
1.	" "	0	14	0
2.	" "	1	7	6
3.	" "	2	2	0
4.	" "	3	10	0
5.	" " (Carton)	4	15	0
5.	" " (Wood)	7	0	0
6.	" " (Wood)	12	10	0

No.		£	s.	d.
0A.	Meccano Outfit	0	7	6
1A.	" "	0	15	0
2A.	" "	0	17	6
3A.	" "	1	10	0
4A.	" "	1	7	6
5A.	" "	4	10	0
5A.	" " (Wood)	6	15	0

Inventors' Accessory Outfit	0	15	0
Clockwork Motor	0	15	0
No. 1 Electric Motor	0	15	0
" 2 " "	1	5	0

No.		s.	d.
1.	Perforated Strips, 12½ in. ½ dozen	2	6
2.	" " 5½ in. "	1	3
3.	" " 3½ in. "	0	11
4.	" " 3 in. "	0	11
5.	" " 2½ in. "	0	11
6.	" " 2 in. "	0	11
8.	Angle Girders ... 12½ in. "	3	9
9.	" " 5½ in. "	2	0
10.	Flat Brackets ...	0	5
11.	Double Brackets ... dozen	2	6
12.	Angle Brackets ...	1	3
13.	Axle Rods ... 11½ in. each	1	3
13A.	" " 8 in. "	0	8
14.	" " 6 in. "	0	5
15.	" " 5 in. "	0	5
15A.	" " 4½ in. "	0	5
16.	" " 3½ in. "	0	4
17.	" " 2 in. "	0	3
18A.	" " 1 in. "	0	3
19.	Crank Handles ...	0	8
19A.	Wheel, 3 in., with Set Screw	1	6
20.	Flanged and Grooved Wheels	2	0
20A.	Pulleys, 2 in., with Set Screw	1	3
21.	" 1½ in., " " "	1	3
22.	" 1 in., " " "	0	10
22A.	" 1 in., without " " "	0	5
23.	" ½ in., " " "	0	5
23A.	" ½ in., with " " "	0	10
24.	Bush Wheels ...	1	3
25.	Pinion Wheels ... ½ in. "	2	0
26.	" " ¼ in. "	1	3
27.	Gear Wheels ... 50 teeth	2	0
27A.	" " 56 " "	2	6
28.	Contrate Wheel 1½ in. "	3	0
29.	" " ¾ in. "	2	6

No.		s.	d.
32.	Worm Wheels	each	2 0
33.	Pawls	"	0 8
34.	Spanners	"	0 8
35.	Spring Clips	doz.	1 3
36.	Screw Drivers	each	0 8
37.	Nuts and Bolts	doz.	1 3
38.	Washers	"	0 5
40.	Hanks of Cord	each	0 3
41.	Propeller Blades	pair	1 3
43.	Springs	each	0 5
44.	Bent Strips, cranked	"	0 5
45.	" " double	"	0 5
46.	" " large	"	0 6
50.	Eye Pieces	"	0 5
52.	Perf. Flanged Plates, 5½ in. × 2½ in.	"	1 3
53.	" " 3½ in. × 2½ in.	"	0 10
54.	" " " Sector	"	0 10
56.	Manual of Instruction—		
	Complete No. 1	"	3 0
	" 2	"	2 0
	" 0	"	0 8
57.	Hooks	"	0 3
58.	Spring Cords, 40 in. long	"	2 0
59.	Collars and Set Screws	"	0 5
60.	Bent Strips, 2½ in.	doz.	2 0
61.	Windmill Sails	each	0 5
62.	Cranks	"	1 0
63.	Couplings	"	1 0
65.	Centre Forks	"	0 4
94.	Sprocket Chains	per yd.	1 6
95.	" Wheels, 2 in.	each	1 3
96.	" " 1 in.	"	0 10
99.	Braced Girders, 12½ in.	doz.	7 6
100.	" " 5½ in.	"	5 0
101.	Healds	"	2 0

MECCANO LTD.

LIVERPOOL, Eng.