

**AUSTRALIA,  
NEW ZEALAND,  
SOUTH AFRICA.**

No.		£	s.	d.
0.	Meccano Outfit	0	8	0
1.	" "	0	14	0
2.	" "	1	7	6
3.	" "	2	2	0
4.	" "	3	10	0
5.	" "	4	15	0
5.	" "	7	0	0
6.	" "	12	10	0

No.		£	s.	d.
0A.	Meccano Outfit	0	7	6
1A.	" "	0	15	0
2A.	" "	0	17	6
3A.	" "	1	10	0
4A.	" "	1	7	6
5A.	" "	4	10	0
5A.	" "	6	15	0

Inventors' Accessory Outfit	0	15	0
Clockwork Motor	0	15	0
No. 1 Electric Motor	0	15	0
" 2	1	5	0

**MECCANO LTD.**

1019/3

# Meccano Price List

**MAY, 1919.**

No.		£	s.	d.
1.	Perforated Strips, 12½ in.	½	dozen	2 6
2.	" "	5½ in.	"	1 3
3.	" "	3½ in.	"	0 11
4.	" "	3 in.	"	0 11
5.	" "	2½ in.	"	0 11
6.	" "	2 in.	"	0 11
8.	Angle Girders	12½ in.	"	3 9
9.	" "	5½ in.	"	2 0
10.	Flat Brackets	...	"	0 5
11.	Double Brackets	...	dozen	2 6
12.	Angle Brackets	...	"	1 3
13.	Axle Rods	11½ in.	each	1 3
13A.	" "	8 in.	"	0 8
14.	" "	6 in.	"	0 5
15.	" "	5 in.	"	0 5
15A.	" "	4½ in.	"	0 5
16.	" "	3½ in.	"	0 4
17.	" "	2 in.	"	0 3
18A.	" "	1 in.	"	0 3
19.	Crank Handles	...	"	0 8
19A.	Wheel, 3 in., with Set Screw	"	"	1 6
20.	Flanged and Grooved Wheels	"	"	2 0
20A.	Pulleys, 2 in., with Set Screw	"	"	1 3
21.	" 1½ in., "	"	"	1 3
22.	" 1 in., "	"	"	0 10
22A.	" 1 in., without	"	"	0 5
23.	" ¾ in., "	"	"	0 5
23A.	" ¾ in., with	"	"	0 10
24.	Bush Wheels	...	"	1 3
25.	Pinion Wheels	¾ in.	"	2 0
26.	" "	½ in.	"	1 3
27.	Gear Wheels	50 teeth	"	2 0
27A.	" "	56 "	"	2 6
28.	Contrate Wheel	1½ in.	"	3 0
29.	" "	¾ in.	"	2 6

No.		£	s.	d.
32.	Worm Wheels	...	each	2 0
33.	Pawls	...	"	0 8
34.	Spanners	...	"	0 8
35.	Spring Clips	...	doz.	1 3
36.	Screw Drivers	...	each	0 8
37.	Nuts and Bolts	...	doz.	1 3
38.	Washers	...	"	0 5
40.	Hanks of Cord	...	each	0 3
41.	Propeller Blades	...	pair	1 3
43.	Springs	...	each	0 5
44.	Bent Strips, cranked	...	"	0 5
45.	" " double	...	"	0 5
46.	" " large	...	"	0 6
50.	Eye Pieces	...	"	0 5
52.	Perf. Flanged Plates, 5½ in. × 2½ in.	"	"	1 3
53.	" " 3½ in. × 2½ in.	"	"	0 10
54.	" " Sector	"	"	0 10
56.	Manual of Instruction—			
	Complete No. 1	...	"	3 0
	" " 2	...	"	2 0
	" " 0	...	"	0 8
57.	Hooks	...	"	0 3
58.	Spring Cords, 40 in. long	...	"	2 0
59.	Collars and Set Screws	...	"	0 5
60.	Bent Strips, 2½ in.	...	doz.	2 0
61.	Windmill Sails	...	each	0 5
62.	Cranks	...	"	1 0
63.	Couplings	...	"	1 0
65.	Centre Forks	...	"	0 4
94.	Sprocket Chains	...	per yd.	1 6
95.	" Wheels, 2 in.	...	each	1 3
96.	" " 1 in.	...	"	0 10
99.	Braced Girders, 12½ in.	...	doz.	7 6
100.	" " 5½ in.	...	"	5 0
101.	Healds	...	"	2 0

**LIVERPOOL, Eng.**